

 RADIOMETER Physics GmbH	Birkenmaastr.10; D-53340 Meckenheim; Germany	Date	2013-06-13
	Atrprop Packing List	Rev	1
		Page	1 / 1
		Auth.	A.Mombauer

Atrprop Packing List

1) Radiometer Box 1

- a) RPG-Hatpro
- b) Dewblower

2) Radiometer Box 2

- a) RPG-90+15
- b) Dewblower

3) Azimuth Positioner

- a) mounted on a wotan pallet including screws in a box.

4) Accessory Box

- a) 1x MPU – main power unit including 9 pol SubD cable to the host PC.
- b) 1x power cable (power cable for radiometers and heaters).
- c) 1x power cable (power cable for azimuth drive).
- d) 1x data cable (fibre optic cable for azimuth drive).
- e) 2x data cables (fibre optic cable for radiometers).
- f) 2x GPS (GPS-Clock).
- g) 2x RS (rain sensor).
- h) 2x heater (heater for dewblower).
- i) 1x IR (infrared radiometer including rain protect housing).
- j) 1x rain protect shield for Azimuth drive.
- k) 2x PC (1x host computer, 1x spare computer, both installed).
- l) 1x power supply (power supply for host PC).
- m) 1x USB Hub (for host PC).
- n) 1x tool bag (tool bag with radiometer tools in a red box).
- o) 1x bag with a lot of small parts (screws, cable fixer, other tools).
- p) 1x package with old Parts (left old parts, not in use anymore after radiometer refurbishing).